

Optimizing Sonar Performance by Managing Acoustics

November 20, 2014

Marisa Yearta and Timothy Gates

WHY ACOUSTIC NOISE IS IMPORTANT

- Excessive ship-related noise can degrade sonar performance
- Degraded sonar performance will impact quality of acquired sonar data
- Reduced sonar performance will increase time required on station to conduct survey operations

WHY ACOUSTIC NOISE IS IMPORTANT

- Once it has been determined a multibeam sonar is functioning properly, the most important factor to consider is contamination with acoustic noise
- Some noise sources are unavoidable, but many sources can be eliminated or mitigated
- Understanding what your noise limiting source is, will greatly enhance your options to improve sonar performance

WHAT IS QUIET?

- Typically 49 dB is used as a quiet ship threshold for 12 kHz systems
- For shallower systems that operate at higher frequencies, the threshold is in the lower 40 dB range
- However, with more information being pulled out of sonar data (water column), the better the signal-to-noise, the better the data quality


TYPICAL SOURCES OF SHIP-RELATED NOISE

- Machinery Noise
- Sonar Interference
- Electronic Noise
- Propeller Cavitation (Hub and Tip Vortex)
- Hydrodynamic Flow Noise
- Appendage Cavitation
- Transients
- Bubble Sweepdown

MACHINERY NOISE

- Machinery noise is typically a lower frequency problem
- Occasionally, higher frequency noise does originate from machinery which can degrade oceanographic sonar background noise levels



USCGC HEALY (WAGB 20)
EM 122 RX NOISE LEVEL
POTABLE WATER PUMP 2 RUNNING
16 AUGUST 2014





USCGC HEALY (WAGB-20)
BOILER FEED PUMP ON VS OFF
EM122 RX NOISE LEVEL
17 AUGUST 2014




USCGC HEALY (WAGB 20) - QUIET




POTABLE WATER PUMP IMPACT




BOILER FEED PUMP 1 IMPACT



BOILER FEED PUMP 2 IMPACT




**E/V NAUTILUS
EM 302 RX NOISE LEVEL
OLD VS NEW SSVS PUMP COMPARISON
5 MAY 2014**




SONAR INTERFERENCE

- Operation of bridge/navigation electronics often degrades sonar performance

NOAA Ship *OKEANOS EXPLORER* (R-337)
DOPPLER SPEED LOG IMPACT - 8 KNOTS
EM 302 RX NOISE LEVEL
7 FEBRUARY 2014




**R/V SIKULIAQ
EM302 RX NOISE LEVEL
0 KTS - FATHOMETER ON VS SECURED
16 JULY 2014**




PROPELLER NOISE


- Propeller cavitation can be loud and is typically present at higher frequencies which can severely impact oceanographic sonars
- Propeller noise is much more prevalent in sonar data in shallow water

**E/V NAUTILUS
EM302 RX NOISE LEVEL
DEPTH COMPARE - 25 PITCH
10 APRIL 2013**





NOAA Ship *OKEANOS EXPLORER* (R-337)
8 KNOTS - DEEP VS SHALLOW WATER
EM 302 RX NOISE LEVEL
6 FEBRUARY 2014




HYDRODYNAMIC FLOW NOISE

- Water flowing over the hull/sonar regions can create noise as the flow becomes turbulent
- Smooth and pristine conditions are ideal
- Biological fouling can be a severe problem


M/V FALKOR

- M/V FALKOR reported significant degradations to sonar performance
- RX Noise levels were significantly increased
- Underhull inspection revealed poor conditions associated with bio-fouling




Propeller cap

A close-up photograph of a propeller cap, which is a dark, circular metal component. The surface is slightly textured and shows some signs of wear and discoloration. The background is a bright, clear blue, suggesting an underwater environment.




Base of blade (aft facing side)

A close-up photograph of the base of a propeller blade, showing the aft-facing side. The metal surface is heavily corroded and covered in a thick, brownish-orange layer of rust. The background is a bright, clear blue, suggesting an underwater environment.



Base of blade
(forward facing side)

A close-up photograph of the base of a propeller blade, showing the forward-facing side. The metal surface is heavily corroded and covered in a thick, brownish-orange layer of rust. The background is a bright, clear blue, suggesting an underwater environment.



Shaft junction (aft facing perspective)

A close-up photograph of the shaft junction, showing the aft-facing perspective. The metal surface is heavily corroded and covered in a thick, brownish-orange layer of rust. The background is a bright, clear blue, suggesting an underwater environment.

Transducer







Plate seam



Bulbous bow



Bolt recess on zinc



RVIB NATHANIEL B. PALMER

- Drydock inspection revealed extremely poor conditions near sonar transducers
- Gaps were noted between transducer faces and ships hull
- Paint conditions were terrible
- Sonar acoustic windows possessed major cracks
- These conditions will significantly degrade hydrodynamic flow noise levels
















R/V SIKULIAQ

- SIKULIAQ was significantly fouled during baseline acoustic testing
- Sonar levels were completely controlled by hydrodynamic flow noise at vessel of 3 knots and above


R/V SIKULIAQ - ADCP




R/V SIKULIAQ – EM 302



R/V SIKULIAQ – EM 302




R/V SIKULIAQ – EM 710




R/V SIKULIAQ – EM 710



**R/V SIKULIAQ
EM 710 RX NOISE LEVEL
60% THRUST - JULY VERSUS SEPTEMBER 2014
15 SEPTEMBER 2014**




R/V SIKULIAQ
EM 302 RX NOISE LEVEL
SPEED VS 30 kHz LEVEL - INTO VS FOLLOWING SEAS
15 SEPTEMBER 2014



BUBBLE SWEEPDOWN

- Bubble sweepdown is created when air from the bow region is sucked under the ships hull
- If it gets to the sonar transducer region it can severely degrade sonar performance

PALMER BUBBLE IMPACT



COMMERCIAL SURVEY LAUNCH

- At any underway speed, random transients were degrading sonar performance
- Problem was more prevalent with any port turn
- Underwater photography was collected with a pole mounted GoPro
- Sonar data dropouts were completely correlated with bubbles impacting sonar transducer face

R/V CELTIC EXPLORER

- Testing conducted on Irish ship R/V CELTIC EXPLORER discovered major bubble sweepdown events
- CELTIC EXPLORER has a bulbous bow (bubble generator)



FIGURE 27

INTO SEAS



FIGURE 28

INTO SEAS



FIGURE 29



FIGURE 30


INTO SEAS

FIGURE 31


R/V SIKULIAQ BUBBLE SWEEPDOWN

- SIKULIAQ has a lot of bubbles
- SIKULIAQ has an icebreaker hull (notorious for bubbles)
- Bubbles were present at all headings

**R/V SIKULIAQ
EM 302 RX NOISE LEVEL
7.5 KTS - 60% THRUST - INTO SEAS
12 SEPTEMBER 2014**




**R/V SIKULIAQ
EM 302 RX NOISE LEVEL
8.4 KTS - 60% THRUST - FOLLOWING SEAS
12 SEPTEMBER 2014**



TRANSIENTS


USCGC HEALY (WAGB-20)
EM 122 RX NOISE LEVEL
80 RPM - OPEN WATER VS THROUGH THIN ICE
17 AUGUST 2014




TRANSIENTS

- During an acoustic evaluation of USNS BRUCE C. HEEZEN (T-AGS 64) high levels were noted in the RX Noise Level
- Acoustic monitoring system aurally revealed the presence of deck work being done
- A ship inspection discovered needle gun activity being conducted


USNS BRUCE C. HEEZEN (T-AGS 64)
EM 122 RX NOISE LEVEL
NEEDLE GUN OPERATION IMPACT
14 APRIL 2014




USNS BRUCE C. HEEZEN (T-AGS 64)
EM 122 RX NOISE LEVEL
NEEDLE GUN OPERATION IMPACT
14 APRIL 2014




USNS MARY SEARS (T-AGS 65)
RX NOISE LEVEL
TRANSIENT NOISE



USNS MARY SEARS (T-AGS 65)
RX NOISE LEVEL
TRANSIENT NOISE



BOTTOM SWATH AT NOISE GOAL



ACOUSTIC MONITORING

- The acoustic posture of a research vessel should be assessed at critical stages during its life
- An initial baseline at construction should always be obtained
- During major sonar upgrades additional baselines should be acquired
- Additionally, periodic assessments should be conducted to ensure the acoustic levels are not degrading sonar performance

CONCLUSIONS...

BASIC PERFORMANCE TENET

QUIETER IS
BETTER!!!